

H. Wilson Company

555 West Taft Drive South Holland, IL 60473

Phone: 800-245-7224 Fax: 800-245-8224 www.hwilson.com sales@hwilson.com

<u>WOH39E</u> Metal Overhead Projector Cart

Parts List

- (1) Shelf
- (1) Cord Wrap
- (2) Side Supports
- (4) 4" Swivel Casters
- (1) Electrical Assembly
- (2) Small Bolts
- (2) Small Nuts
- (8) Shelf Screws

Tools Required

Phillips Head Screwdriver Slotted Screwdriver

Table should only be pushed by authorized adults. Never pull table.

TWO PEOPLE SHOULD ASSEMBLE THIS CART



Cart Assembly Instructions:

- 1. Separate and Identify Parts.
- 2. Attach shelf with logo to side panel using shelf screws provided. Secure using screwdriver. Attach lower shelf with no logo in the same manner as shown in diagram below.
- 3. Follow same procedure for other side panel.
- 4. Logo on shelf is the front. Tap casters with brake in the front and casters without brake in the back.

Electrical Assembly Instructions:

- 1. Turn cart so that the side you want to install the electrical assembly onto is towards you. Place Metal Cordwrap over top shelf, lining up pre-drilled holes.
- 2. Place the two screws through the holes of the electrical.
- 3 Fit the electrical assembly over the holes on the side of the shelf so that the screws are going through the holes.
- 4 Secure screws with wingnuts from underneath the shelf.

