



**H. Wilson Company**  
555 West Taft Drive  
South Holland, IL 60473  
Phone: 800-245-7224  
Fax: 800-245-8224  
www.hwilson.com  
sales@hwilson.com

# WOH29E **Metal Overhead Projector Cart**



## **Parts List**

- (1) Shelf
- (1) Cord Wrap
- (2) Side Supports
- (4) 4" Swivel Casters
- (1) Electrical Assembly
- (2) Small Bolts
- (2) Small Nuts
- (8) Shelf Screws

## **Tools Required**

- Phillips Head Screwdriver
- Slotted Screwdriver

**Table should only be pushed by authorized adults. Never pull table.**

## **Cart Assembly Instructions:**

### **TWO PEOPLE SHOULD ASSEMBLE THIS CART**

1. Separate and Identify Parts.
2. Attach shelf with logo to side panel using shelf screws provided. Secure using screwdriver.
3. Follow same procedure for other side panel.
4. Logo on shelf is the front. Tap casters with brake in the front and casters without brake in the back.

## **Electrical Assembly Instructions:**

1. Turn cart so that the side you want to install the electrical assembly onto is towards you. Place Metal Cordwrap over top shelf, lining up pre-drilled holes.
2. Place the two screws through the holes of the electrical.
3. Fit the electrical assembly over the holes on the side of the shelf so that the screws are going through the holes.
4. Secure screws with wingnuts from underneath the shelf.

